

Vanishing Oil QD

Features & Benefits

- No Residue
- Non-Reactive to Metals
- Ideal for Drawing & Stamping
(light gauge material)
- Works on Ferrous &
Nonferrous Metals
- Excellent Lubrication

PRODUCT DESCRIPTION

Ashburn Vanishing Oil QD is a very low viscosity oil which is fortified with mild extreme pressure additives. It will evaporate completely with no residue.

This product leaves an excellent finish on cut, drawn or stamped parts.

APPLICATION

Ashburn Vanishing Oil QD is ready to use, do not dilute.

TYPICAL ANALYSIS

APPEARANCE: Clear Oil
 DENSITY: 6.42 LB/GL
 FLASH POINT: > 177°F (PMCC METHOD)
 VISCOSITY: 2.2 - 3.1 cSt @ 40°C
 SULFUR: NONE
 CHLORINE: NONE
 PHOSPHOROUS: NONE

PACKAGING

E-7530-14	1 Gallon (4/case)
E-7530-05	5 Gallon
E-7530-55	55 Gallon
E-7530-275	275 Gallon

NOTES

- Use Ashburn Machine Cleaner for quick and thorough pre-cleaning of machine tools and coolant systems.
- Consult Ashburn prior to use on metals or applications not recommended.
- Unless recommended by Ashburn, this product should not be mixed with metal working fluid additives.



7403 Wright Rd. Houston, TX 77041
 ph: 832.399.1000 fax: 832.399.1010
 www.ashburnchemical.com

